



TASK 71238

Date Called in	12/19/2022
Date Scheduled	12/27/2022 1:00 PM

City Of Orono
Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1790 Shadywood Road
PID:	1711723210025

Owner Information			
Name:	Joshua and Caitlin Mateffy *Realtor Rita Pederson 612-718-6579		
Mailing Address: (if different from Property)	27680 Island View Road Shorewood, MN 55331		
Phone:	608-345-2957	Email:	jmateffy@blackedge.com

Inspector Information			
Name:			
Company/ Organization		License number:	
Phone:		Email:	

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	X	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	+	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	X	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)		X
Notes:	Roots in Line		
Toilet Removed For Inspection:	o Yes <input checked="" type="checkbox"/> No		

Inspectors Signature: Scott Brandon	Date: 12-27-22
Owners Signature:	Date:

City Review			
<input type="checkbox"/> Compliant	<input checked="" type="checkbox"/> Corrective Action Required		
Certificate of Compliance Expires:	Corrective Action Due by: 03/27/2023.		
Date: 12/27/2022	Signature: Kellie Hoehn		
	Name: Kellie Hoehn		

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	4" PVC cast , clay
Overall Condition of Service Pipe	cast dirty

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.

This report must include a digital copy of the televising.

Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint - Infiltration
0	Entered. Cleanout in laundry room
23'	Cleanout - 4"
26'	cast cast to PVC
87'	PVC to cast
142 -	Clay to PVC
144'	Y - Possibly neighbor
170'	roots
173'	roots
179'	roots
185 -	roots @ Baint
190'	roots - clay to PVC towards main
195'	main
Notes:	