

Date Called in 11/17/2023 Date Scheduled 11/27/2023 10:30 AM

City Of Orono City Of Orono 11 | 28 | 23 | 1:00 AM Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		669 Sandstone Circle					
PID:		3311823110038					
			ò			*)	
		Owner In	formation				
Name:	Linda	Ortner					
Mailing Address: (if different from Property)							
Phone:	952-9	13-6598	Email: lindaortner2015@g	mail.com			
Inspector Information							
Name:	Hunter/Brandon						
Company/ Organization		City of Croise	License number:				
Phone:			Email:	7			
ÿ.				12			
		Inspe	ection				
System	Stand				Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation	Founda	ation drains are underground pi	pes that collect storm water fro		,		
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:		(
ŀ	CERTIFIED EXPIRES: 11/28/2033						
Toilet Removed	o Yes & No						
For Inspection:							
1							
Inspectors Signatu	re: \angle	5 in Mun		Date:	11/28/	C.3	
1 C Programme			Date:	, ,			
,							
City Review							
Certificate of Compliance Expires: 11/28/2033 , Corrective Action Due by:							
Date: Signature: Lille Holin							
11/28/2023 Name: Kellic Hoen							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	3" Puc
Overall Condition of Service Pipe	6000

Please note all connections, fittings, points of concern on service line including infiltration, tree root,							
cracks, misaligned joints, etc. This report must include a digital copy of the televising.							
Feet							
Example:	Comment						
0	Start for 4" cleanout in NE corner of Basement						
1-10	Misaligned joint –Infiltration						
	- And angles joint Annualist						
0							
	3° PVC Stack under stairway in Basement						
0,	2 400						
	Double wie keel neighbus Contant Drep down to Commen 12th of line						
l W	Double will love						
	Contant Ales down to Convin 18st of line						
NI-4-							
Notes:							