## Ende Septic Service, LLC, MPCA Lic #L2654

**Maintenance Inspection Form** 

ers. MN 55374	Maintenan	ee inspection roim				
5 3	□ Tristan 🏿 Brandon 🗆 Sc	ott □ Dylan □ Seth				
	7					
y $\square$ Other Thuk ${\cal Y}$	Disposal location: ☐ Land	ap 💢 Treatment plant				
	Invoice					
Date: 9-26-23  Name: Shawn Wischmeler  Address: 540 Big Island  City/State/Zip: Excelsior		Description:  Total Cost of Service:  Payment Method: □ Check □ Cash □ Credit				
					Control of the Contro	Maintenance hole cover is damaged, cracked, unsecured, or appears to be structurally sound
				□ Yes 🏚 No	□ Yes <b>A</b> No	□ Yes 🗗 No
□ Yes □ No	□ Yes □ No	□ Yes □ No				
□ Yes □ No	□ Yes □ No	□ Yes □ No				
□ Yes ÆNo	□ Yes �No	□ Yes <b>②</b> No				
tenance hole; if so, were co- pipe; if through pipe, did hor conal issues or unsafe condi	wers secured in place? Tyes meowner sign off? Tyes	□ No age tanks in this system, i.e.,				
Tank #2 □ Yes □ No	Pump Tank ☐ Yes No	System				
□ Risers leaking □ Baffles	☐ Structural integrity ☐ Risers leaking ☐ Baffles ☐ Electrical issues ☐ Non-domestic waste	☐ Mound ☐ Elevated drainfield ☐ Pressure bed ☐ Trenches ☐ Ponding/surfacing				
	Tank leaks below the designed operating depth  Tyes No  Yes No  Yes No  Yes No  Yes No  Yes No  Other Yes No	Tristan   Brandon   Scores   Scores   Scores   Disposal location:   Land   Invoice   Description:   Total Cost of Service:   Payment Method:   Check   Check				