Ende Septic Service, LLC, MPCA Lic #L2654 **Maintenance Inspection Form** 24910 Territorial Road • Rogers, MN 55374 Phone: 763-428-4489 ☐ Tristan ☐ Brandon ☐ Scott ☐ Dylan ☒ Seth email: info@endeseptic.com Disposal location: ☐ Land ap ☐ Treatment plant ☐ Maintenance ☐ Emergency ☐ Other \_\_\_\_\_ Date: Invoice Name: Description: Total Cost of Service: 465.00 Address: City/State/Zip: Payment Method: ☐ Check ☐ Cash ☐ Credit Tank leaks above the Tank (check if present) Tank leaks below the Maintenance hole cover is designed operating damaged, cracked, designed operating unsecured, or appears to be depth depth structurally sound □ Yes DNo Septic/holding Tank #1 □ Yes 1 No □ Yes Gallons: ☐ Yes ☐No ☐ Septic/holding Tank #2 ☐ Yes ☐ No □ Yes No No Gallons: ☐ Yes No ☐ Yes 🔼 No N Pretreatment Tank □ Yes No Gallons: Pump Tank □ Yes No No □ Yes □ No □ Yes No. Gallons: Did you measure the accumulation of scum and sludge? □ Yes □ No Access point: □ Cover/maintenance hole; if so, were covers secured in place? □ Yes □ No Access point: ☐ Inspection pipe; if through pipe, did homeowner sign off? ☐ Yes Did you identify any operational issues or unsafe conditions while assessing the sewage tanks in this system, i.e., cracked tanks, missing baffles, broken covers, etc.? If so, explain in comments below. Pump Tank ☐ Yes ☐ No Tank #1 □ Yes □ No Tank #2 ☐ Yes ☐ No System ☐ Structural integrity ☐ Structural integrity Mound ☐ Structural integrity ☐ Elevated drainfield ☐ Risers leaking ☐ Risers leaking ☐ Risers leaking ☐ Pressure bed □ Baffles □ Baffles □ Baffles ☐ Non-domestic waste □ Non-domestic waste ☐ Electrical issues ☐ Trenches □ Non-domestic waste □ Ponding/surfacing ☐ Other: ☐ Effluent filter cleaned? ☐ Yes ☐ No

Comments: (Ireat condition