

Date Called in 5/16/2024 Date Scheduled 5/20/2024 7:30 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

		N					
Property Address:		1025 Tonkawa Road					
PID:		0811723240003					
4				V 8			
		Owne	r Information				
Name:	Hugh Neeson						
Mailing Address: (if different from Property)							
Phone:	952-2	37-3149	Email: neeson@mchs	i.com	r		
` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` ` `						2	
		Inspect	or Information				
Name:		<u> </u>	,				
Company/ Organization			License number:	3			
Phone:		7 J 2	Email:				
A HOLLEY							
		Ir	spection	Par Bara			
System	Stand		•		Pass	Fail	
Roof Drains			ns should not be connected to the	sanitary			
	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.				r - T		
Foundation	Foundation drains are underground pipes that collect storm water from						
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Natas	specific	ations. (Details on back o	i this sheet)				
Notes:	A	11 900/					
Toilet Removed	° Yes	No No					
For Inspection:							
•							
					. > ~	211	
Inspectors Signature: 5 (att) JUST in			Date:	500-	-97		
Owners Signature:		-11/		Date:		'/	
J							
		Cit	y Review				
Compliant Corrective Action Required							
Certificate of Compliance Expires: 5/20/2034 Corrective Action Due by:							
Date: Signature: Kelleschoen							
5/20 /2024 Name: Kellic Hoen							
	•						

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.				
Feet	Comment			
Example:				
0	Start for 4" cleanout in NE corner of Basement			
1-10	Misaligned joint –Infiltration			
0				
	CRAnott in mechanical consort botton of a			
	Cleanort in mechanical room at bottom of stairs			
	TOLATI			
MIC				
HOT				
()	1-0			
46	くで乗りのリナ			
,				
•				
- T	r lan s			
57	- CAMOUT			
	Cleanort Cast to			
7 2	0/10/170			
70	1712S			
}				
, ,	and to have			
111	CAST TO DIK			
1/2/	N. 10			
	15.14.16			
Notes:				
	Looks good			

