



Date Called in	
Date Scheduled	

City Of Orono
Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	125 Chevy Chase Drive
PID:	3611823410018

Owner Information			
Name:	Robert McCanahan		
Mailing Address: (if different from Property)			
Phone:	612-554-6423	Email:	Rmccla98@gmail.com

Inspector Information			
Name:			
Company/ Organization	City of Orono John's Sewer & Drain Cleaning	License number:	
Phone:	952-249-4686 612-756-7394	Email:	

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.		
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.		
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	✓	
Notes:	The video is pretty blurry and there is a lot of sag in the pipe that is holding water, with it being that way the camera is underwater and we cannot see the pipe 100%, but from what I can see there isn't signs of I&I. The sag in the pipe is no worry for the city. I do recommend that a new clearer video is provided. We can pass this as long as there is an understanding that we are not liable if something happens that we were unable to see in the video, due to it being blurry or being underwater. - Jimmy Nelson, Supervisor		
Toilet Removed For Inspection:	<input type="radio"/> Yes <input type="radio"/> No		

Inspectors Signature:	Date:
Owners Signature:	Date:

City Review	
<input checked="" type="checkbox"/> Compliant	<input type="checkbox"/> Corrective Action Required
Certificate of Compliance Expires: 5/22/2035	Corrective Action Due by:
Date: 5/30/2025	Signature: <i>Heather Smieja</i>
	Name: Heather Smieja

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.
This report must include a digital copy of the televising.

Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration
0	Video #1 0' - 2' Outside clean out 4" PVC to 4" cast iron, 50' - 70' Belly, 75' clean out, 82' - 115' Belly Video #2 137' main, 0- outside clean-out
Notes:	