Task # 96229



Date Called in	
Date Scheduled	7/14/2025

## City Of Orono Point of Sale Sanitary Sewer Service 1&1 Compliance Inspection Form

Property Address:	1105 Brown Road South
PID:	1011723240004

Owner Information				
Name:	Nicole Middendorf			
Mailing Address:				
(if different from				
Property)				
Phone:	612-360-4355	Email:	Nicole@prosperwell.com	

Inspector Information			
Name:	Jimmy Nelson		
Company/ Organization	City of Orono	License number:	
Highview Plumbing			
Phone:	952-249-4686   612-916-1685	Email:	

	Inspection				
System	Standard	Pass	Fail		
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	-/			
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	V			
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	1			
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)		<b>\</b>		
Notes:	Mineral deposits at 113' and 125' that needs to be repaired.				
Toilet Removed For Inspection:	∘ Yes ∘ No				

İ	Inspectors Signature:	Date:
	Owners Signature:	Date:

		City 1	Review	,		
Compliant	•	·	>	Corrective	Action Required	(
Certificate of Compliance E	xpires:		Correc	tįvę Action	Due by: 10/14/2025	,
Date: 7/16/2025	Signature:	Heath	ar Si	rlejdi		
//10/2023	Name:	Heather	r Smieja	U		

## **Service Line Inspection Details**

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising. Feet Comment Example: Start for 4" cleanout in NE corner of Basement Misaligned joint -Infiltration 1-10 4" STACK C.O. FN MECH. ROUM 96' TEST WYE?

995 4"CAST

1135 MENERAL DEMOSSIT?

1245 MENERAL DEMOSSIT?

141 PUL

141 PUL

141 MAEN Notes: