

Date Called in Date Scheduled 8/07/2025

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		2610 West Lafayette Road						
PID:		2111723240043						
Owner Information								
Name:								
Mailing Address: (if different from	-	-						
Property)	roperty)							
Phone:	612-382-5746 Email: Flipflopsonly@gmail.com							
Inspector Information								
Name:		Gerve M. Jimmy Nelson						
Company/ Organization				License number:				
		City of Orono						
Phone:		612-724-8253 952-249-4686		Email:				
			Insp	ection				
System	Stand					Pass	Fail	
Roof Drains				should not be connected to the sound outside of a building. If the		İ		
				sewer, disconnect them, plug an		İ		
				ing a non-shrink permanent mat		ľ		
				nd outside the building.				
Foundation	Foundation drains are underground pipes that collect storm water from							
Drains	around the base of a building and into a sump basket, where it is then							
	pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.							
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters							
Sump rumps	basements or crawl spaces and pump it away from the house. The basic sump							
	system includes drain tile, a sump pit, a sump pump, a float or switch, and a							
	drain line. Sump pumps should not be connected to the sanitary sewer.							
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the							
Line	main line, shall be in a safe and functional condition and shall be free from all							
	leaks, failures including but not limited to partially collapsed sections or tree							
	root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)							
NI-4	specific	ations. (Deta	uls on back of th	nis sheet)				
Notes:	Review of the video submitted of the sanitary sewer line looked to be in compliance through the							
	183ft that was scoped. The City of Orono passes this inspection based on the length of pipe we							
	can see but cannot guarantee anything past the point that was unable to be reached Jimmy							
	Nelson, Supervisor of Sewer and Water							
Tailet Damassad	- X7 - X1							
Toilet Removed	o Yes	o No				•		
For Inspection:								
		. <u> </u>					-	
Inchestana Cianatur					Datas			
Inspectors Signature:			Date:					
Owners Signature: Date:								
C' P								
City Review								
\[\] Compliant \[\] Corrective Action Required Certificate of Compliance Expires: 8-07-2035 Corrective Action Due by:								
_								
Date: 8-11-2025			Signature: Kenty Sun					
		Name:	Heathe	r Smieja				

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.						
This report must include a digital copy of the televising.						
Feet Example:	Comment					
0	Start for 4" cleanout in NE corner of Basement					
1-10	Misaligned joint –Infiltration					
	- Manual State of Control of Cont					
0						
Notes:						