TASK 62838

Date Called in 3/22/2022 Date Scheduled 3/23/2022 4:00 PM 1:30



City Of Orono

Poin	at of Sa	le Sanitary Sev	ver Servi	ce I&I Co	mpliance Insp	ection Forr	n		
Property Address:		1375 Park Drive)						
PID:		0711723410079							
	I								
			Owner In	nformation					
Name:	Mike R	losolanka							
Mailing Address:	8465	Kelzer Pond [Drive						
(if different from Property)									
Phone:	612-4	08-4823		Email:	mike@rosolar	nka.com	noty		
				<u> </u>				1	
		, І	nspector	Informatio	n				
Name:		Brian	Ju	15711					
Company/ Organizatio				License	number:				
Phone:				Email:					
	000000000000000000000000000000000000000								
	-	_	Insp	ection		6	T /		
System	Stand						Pass/	Fail	
Roof Drains	sewer b	rains and leaders Rout should discharg are connected to the tions to the sanitary	e to the gro e sanitary s	ound outside ewer, discor	of a building. If t nnect them, plug a	he roof ny open			
		the roof drains on					/		
Foundation Drains	around	tion drains are und the base of a build I outside of the bui	ing and into	o a sump bas	sket, where it is th	en			
		anitary sewer.					/		
Sump Pumps	baseme system	oumps are designe nts or crawl spaces includes drain tile,	and pump a sump pi	it away from t, a sump pu	m the house. The amp, a float or sw	basic sump vitch, and a			
		ne. Sump pumps sh						├	
Sewer Service Line	Sewer I main lin leaks, f root int	y Sewer Inflow & Danitary Lines. All sanitary ne, shall be in a safailures including brusion. The sanitar eations. (Details or	sewer lines e and funct ut not limit y sewer lin	s serving Pro tional condit ed to partial es shall mee	perty, from the ho ion and shall be fi ly collapsed section	ouse to the ree from all ons or tree			
Notes:									
Toilet Removed For Inspection:	o Yes	o No							
i or mapeedon.					****************		A 100 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		
Inspectors Signatu		120				Date:	3-23	22	
Owners Signature	:				Sangalarin in the sangalarin i	Date:			
			~···						
			City.	Review	7	D ' 1			
☐ Compliant	1!	D!			Corrective Action			220	
Certificate of Com	ipiiance	· · · · · · · · · · · · · · · · · · ·	1/.	Correctiv	re Action Due b	y: Q/;	23/20	16.2	
Date:		Signature:	Kl	MUC D	Joen				
		Name: K	e/11e.	Hoen					

Service Line Inspection Details

Weather Conditions:		•
Approximate Depth of Service	·	
Type and Size of Service	Y" CIP	
Overall Condition of Service Pipe		

Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.
Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint —Infiltration
1-10	Wisanghed Joint — mintration
0	€*
:	
	o' cleanent in well from CIP
	0' clearent in well room, CIP 142-107'- repair: pipe, PVC 4" 150' roots in Joint 197' main, Seeded CIP
	150' roots in Joint
Notes:	197 main, Beadelow CIP
votes:	