## Task 68644



## Date Called in Date Scheduled 10/12/2022 8 AM

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Poi	nt of Sa	ale Sanitary Sewer Serv	ice I&I Compliance Inspec	tion For	m			
Property Address:		1180 Garden Court						
PID:		0711723230031						
			-					
		Owner 1	Information					
Name:	Keeg	gan Wallace	*					
Mailing Address:					IFIED			
(if different from				EXPIRES:	10/12/20	32		
Property)	612 /	612-594-9898 Email: Kergan. lakelande				1 0000		
Phone:	1012-	094-9090	Lilian.   Kilami.ink	-CIAVICI C	griai	11.007		
		Inspector	Information					
Name:		Inspector						
Company/ Organi	zation		License number:					
Phone:			Email:					
			pection		T =5	I		
System	Stand		land and the comment of the first	au itaur	Pass	Fail		
Roof Drains	Roof d	rains and leaders Root drains but should discharge to the gr	should not be connected to the sound outside of a building. If the	annary roof	/			
	drains	are connected to the sanitary	sewer, disconnect them, plug any	open	/			
			ing a non-shrink permanent mate	rial, and	"			
Foundation		t the roof drains onto the ground	pipes that collect storm water fro	m				
Drains			to a sump basket, where it is then		1./			
Diams		_	indation drains should not be con	nected				
a D		sanitary sewer.	are surface or ground water th	at antere	1			
		pumps are designed to capture surface or ground water that enters ents or crawl spaces and pump it away from the house. The basic sump						
	system	includes drain tile, a sump p	oit, a sump pump, a float or swit	ch, and a	$\mid V \mid$			
			be connected to the sanitary sewe		ļ			
Sewer Service	C T AN S D C C C AN A				/			
Line	main line, shall be in a safe and functional condition and shall be free from all							
	leaks, t	failures including but not limi	ited to partially collapsed section	s or tree				
		cations. (Details on back of t	nes shall meet the City Code stan this sheet)	dards and				
Notes:	Бреси	outons (Dounts on Such et al.			<u> </u>			
Toilet Removed	o Yes	○ Yes ○ No						
For Inspection:								
Ingnostana Cionata	11101	/ <del>-</del>		Date:	10/1-	1197		
Inspectors Signature: Owners Signature:			Date:		wille			
Owners Signature	· ·		7.00 pm	Date.				
,		City	Review					
			☐ Corrective Action	Required				
Certificate of Con	npliance	e Expires: 10/12/2032	Corrective Action Due by					
Date:	1	Signature:	lleoHoen					
10/12/2022								

## **Service Line Inspection Details**

Weather Conditions:			
Approximate Depth of Service			
Type and Size of Service	H" PYC	N" SDR-35	
Overall Condition of Service Pipe	GOOD		

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.							
Feet	This report must include a digital copy of the televising.  Comment						
Example:	Comment						
0	Start for 4" cleanout in NE corner of Basement						
1-10	Misaligned joint –Infiltration						
0	4" PVC willty room cleanoust						
0	14. bAC miling 1001.						
00'	dia = +						
28'	Cleanow						
	Cranout						
96	Cicanola						
ا م	cleanout  50R35 to sch 40 PVC  Main						
102'	DNK 28 00 001 12 1						
•							
1201	$M_{cl}$						
(C.)	1"1417						
Notes:							
notes:							