## RONO SHOPLES

## TASK 75240

 Date Called in
 6/1/2023

 Date Scheduled
 6/2/203
 10:00 AM

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address		205 Tanks Aug						
Property Address:		295 Tonka Ave						
PID:		0511723130028						
		Owner	Information	1				
Name:	Nata	llie Jamieson	*****				***************************************	
Mailing Address:	1	9723 Chisholm Trail						
(if different from Property)	Corcoran, MN 55340							
Phone:	612-666-1331 Email: bertucci.natalie@gmail.con							
		Ingneste	r Informatio	\n				
Name:		1 Cen / Brancher	і штоппанс	Ш				
Company/ Organiz	zation	City of Drone	License	number:				
Phone:			Email:			· · · · · · · · · · · · · · · · · · ·		
			pection					
System	Stand				•.	Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open				1			
de la constitución de la constit	connective redirection	connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.			V			
Foundation		ation drains are underground				,		
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.							
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					V		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					V		
Notes:	вреси	COURTER OF CHARLES					<u> </u>	
Toilet Removed For Inspection:	○ Yes	s o No				Hara		
Inspectors Signatu	ıre: 🖊	5 M			Date:	6/2	175	
Owners Signature					Date:			
		Qi.	Dovices					
Compliant		City	Review	Corrective Action	Required			
	nliano	e Expires: 6/5/2033		ve Action Due by				
	пинанс		COLICULY	, o z kouon Duo Uy				
Date:	<u>.p</u>	Signature:	1/18	Hoen				

## Service Line Inspection Details

Weather Conditions:		
Approximate Depth of Service		
Type and Size of Service	4" Skh 40	-
Overall Condition of Service Pipe	6000	

Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.						
Feet	Comment						
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration						
0,	Busement Utility Room 3" cleanout NW corner pvc to Abs						
2'	puc to Abs						
6Z	Y in Pipe						
1431	Main						
Notes:	٦٠						