Ende Septic Service, LLC, MPCA Lic #L2654

Maintenance Inspection Form

| 24910 Territorial Road • Ros Phone: 763-428-4489 email: <u>info@endeseptic.com</u> | | □ Tristan 🗗 Brandon 🗆 Sco | ott □ Dylan □ Seth |
|--|--|--|--|
| ☐ Maintenance ☐ Emergence | ey 🗆 Other | Disposal location: 10 Land | ap □ Treatment plant |
| Date: 9-19-23 | | Invoice | |
| Name: Tim Ferske Address: 765 Dickey Lake Dr. | | Description: Total Cost of Service: 4395.00/ | |
| | | | |
| Tank (check if present | Tank leaks below the designed operating depth | | Maintenance hole cover is damaged, cracked, unsecured, or appears to be structurally sound |
| Septic/holding Tank #1 Gallons: 1,000'S | □ Yes 🏚 No | □ Yes PNo | □ Yes ♠No |
| Septic/holding Tank #2 Gallons: | □ Yes 🏚 No | □ Yes □ No | □ Yes Ø No |
| ☐ Pretreatment Tank Gallons: | □ Yes □ No | □ Yes □ No | □ Yes □ No |
| ◯◯ Pump Tank Gallons: | □ Yes 🛕 No | □ Yes 🖻 No | □ Yes 🗗 No |
| Access point: Cover/mai Access point: Inspection Did you identify any operate | pipe; if through pipe, did ho ional issues or unsafe condi | No Yes No vers secured in place? Yes meowner sign off? Yes tions while assessing the sewaso, explain in comments below | ∃ No age tanks in this system, i.e., |
| Tank #1 □ Yes 🖎 No | Tank #2 □ Yes 💆 No | Pump Tank ☐ Yes ♠No | System |
| ☐ Structural integrity ☐ Risers leaking ☐ Baffles ☐ Non-domestic waste | ☐ Structural integrity ☐ Risers leaking ☐ Baffles ☐ Non-domestic waste | ☐ Structural integrity ☐ Risers leaking ☐ Baffles ☐ Electrical issues ☐ Non-domestic waste ☐ Effluent filter cleaned? ☐ Yes ☐ No | ☐ Mound ☐ Elevated drainfield ☐ Pressure bed ☐ Trenches ☐ Ponding/surfacing ☐ Other: |
| Comments: | | | |