

TASK 82118

Date Called in 1/24/2024
Date Scheduled 1/25/2024 9:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

TESHOR						
Property Address:		3460 Livingston Ave				
PID:		1711723430017				
			0		,	,
N	I/ av du		nformation			
Name:	Kevin and Georgianna BOE					
Mailing Address: (if different from Property)	612-965-8474-Carolyn					
Phone:	Email: Carolyn@MissLakeshore.com					
		Inspector	Information			
Name:		Tustin Miel				
Company/ Organizatio		John Hell	License number:	,		
Phone:		651-861-3178	Email:	jmieli	1000	ron
		Τ		J		
Crustom	Stand		pection		Pass	Fail
System Roof Drains			should not be connected to the s	sanitary	1 455	Fall
Roof Dianis	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.					
Foundation	Foundation drains are underground pipes that collect storm water from					
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.					
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					
Notes:					el di	
Toilet Removed For Inspection:	○ Yes No					
T		10.		Datas	1/>= /	311
Inspectors Signature:				Date:	1/85/	29
Owners Signature: Date:						
		City I	Review			
Compliant Corrective Action Required						
Certificate of Compliance Expires: 01 25 2034 Corrective Action Due by:						
Date: Signature: Kulletoen						
01/25/2024 Name: Kellie Hoen						

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	A, BAC
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.					
This report must include a digital copy of the televising.					
Feet	Comment				
Example:					
0	Start for 4" cleanout in NE corner of Basement				
1-10	Misaligned joint –Infiltration				
0					
	with the second				
÷					
	105 main				
Notes:					
×					