### TASK 86555

Date Called in

8/13/2024

Date Scheduled -8/15/2024 10:30 AM

# City Of Orono

Poi	nt of S	ale Sanitary Sewer Service I&I Compliance Inspection	n Forn	1 8(1	41/2024			
Property Address:		3721 Casco Ave						
1 0		2011723310058						
,		. Kar			300			
		Owner Information						
Name:	Mamie Jin and Doug Welty							
Mailing Address: (if different from Property)								
Phone: 612-281-1414 Email: mmj1027@yahoo.com					= 4			
			A. 6903 10					
		Inspector Information						
Name:		1 7						
Company/ Organi	zation	License number:						
Phone:		Email:						
	3							
		Inspection						
System	Stand	NO. 11 CO. 11 CO		Pass	Fail			
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.							
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.							
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.							
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)							
Notes:			A CO	5-319	٥			
90 0	CAN'T get CAMERA down line, \$3-300 bende bind up camera Books @ 100'							
Toilet Removed For Inspection:	o Yes	₩No	, f )		, "1			
6 :								
Ingnactors Cianata	ıro:	1	Data		- 1			
Inspectors Signature:			Date:					
Owners Signature: Date:			Daic.					
		City Review						
- C 1' '		Oity ROYIOW			A CONTRACTOR			

City Review —						
□ Compliant		✓ Corrective Action Required				
Certificate of Compliance Expires:		Corrective Action Due by: (2 19 20)	24			
Date:	Signature:	Metour				
8 19 2024	Name: Kellie H	oen				

## **Service Line Inspection Details**

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	CTP. VCP. PVC
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.					
This report must include a digital copy of the televising.					
Feet	Comment				
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration				
0					
	28' (160 5 G14+				
	Pa 0.100(1) 0.0(1)				
	Sul Belly Stops				
	83' Belly Stants				
	opperate 93°CIP				
	qu' Puc 100 mots				
	103, A,1 ACB				
	138' main 4" SCLYO				
	Som the sales and the sales				
Notes:					