## Task 64967



## Date Called in 5/26/2022 Date Scheduled 5/27/2022 8:30 AM

## City Of Oromo Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

RESHOP		,	• •	a je	$z_{i}$	
Property Address:		3635 Togo Road		- 4 A		
PID:		1711723310053		X-X-	444	
				***	-	
		Owner In	ıformation			
Name:	Jame	es L Cousin	-			
Mailing Address: (if different from Property)						
Phone:	612-3	85-7589	Email:  cousinjim053@gn	nail.com		
	.1		<u> </u>		£1.	
		Inspector I	Information			
Name:		Brian / Bran	<del></del>			
Company/ Organization		City or Orano	License number:			
Phone:			Email:			
			ection			
System	Stand		111		Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.					
Foundation	Founda	ation drains are underground pi	ipes that collect storm water from			
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.					
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary					
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					
Notes:	Rock at Soints From Rock					
Toilet Removed For Inspection:						
. 1						
		1	/			
Inspectors Signature:				Date: 5/27/	22	
Owners Signature:				Date:		
City Review						
□ Compliant			Corrective Action Required			
Certificate of Compliance Expires:			Corrective Action Due by: 8/27/2022			
Date: Signature: Killiethoen  Signature: Killiethoen						
		V <del></del>				

## Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	4" Clay
Overall Condition of Service Pipe	Bed

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.					
Feet	Comment				
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration				
M,	Roots at Soirt O' Basemont M' Cleanout  Y-in Pipe  Roots of Joint  Roots of Soint  Roots of Soint  Roots of Soint  Roots of Soint  13' Roofs of Soint  17' Roots of Soint  Roots of Soint  123' Roofs of Soint  23' Roofs of Soint				
12	-boots at Joint 23' Roots at Joint				
46					
Notes:					