Task 68104



Date Called in 9/23/2022 Date Scheduled 9/26/2022 10 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Timor		<i>j</i>	F				
Property Address:		746 Tonkawa Road					
PID:		0511723340005					
		Owner Ir	nformation				
Name:	Edwa	ard A and Mary T Caldw	/e	CERTIFII	FD		
Mailing Address: (if different from Property)			EXF	71RES: <u>9/</u>	26/203	32	
Phone:	612-	400-3726	Email: e.caldwell@mcl	nsi.com			
		, Inspector l	Information				
Name:		Brandon/ Shot	in				
Company/ Organization		City of Orono	License number:				
Phone:			Email:				
			ection		T =	Γ	
System	Stand		1 - 11 - 41 1 - 41		Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation	Founda	ation drains are underground p	ipes that collect storm water from				
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	•	/					
Toilet Removed	○ Yes 6 No						
For Inspection:							
					~/-	/	
Inspectors Signature:				Date:	7-2		
Owners Signature:			WAR	Date:			
	NEW 25 - 10 - 10 - 10 - 10 - 10 - 10 - 10 - 1						
Ja		City F	Review				
Compliant Corrective Action Required							
Certificate of Compliance Expires: 9/24/2032 Corrective Action Due by:							
Date: Signature: Kullettoch							
9/24/2022		Name: Kellic Ho	cn				

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	14" PVC 4" CONT 6" Abs
Overall Condition of Service Pipe	60ed

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.						
Feet	Comment					
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration					
O ,	Whilily Room 3" Cleanout					
F	Cost to PVC					
gl' . Go Notes:	Absto Cast Main 31 Cleanant Landy room Basement					