TASK 72135



Date Called in 2/3/2023 Date Scheduled 2/6/2023

City Of Orono

Poi	nt of Sa	ale Sanitary Sewe	r Serv	ice I&I Com	ipliance Inspe	ction For	m		
Property Address:		2745 ETHEL AVE							
PID:		2011723240016							
		C	wner I	nformation					
Name:	Ambe	er Peifer				CER	TIFIED		
Mailing Address:		EXPIRES: 5/2/2033							
(if different from Property)						La P 11			
Phone:	612-702-7420 Email: ampeifer@gmail						com		
T Hone.	1012	02 1 720		Lanan.	ampener	<u>wgman.</u>	30111		
		Ins	nector	Information					
Name:		4.11	pecioi	momunon					
Company/ Organi	zation		License number:						
Phone:			··········	Email:					
Filone.				Ellian.					
			Inst	ection					
System	Standard						Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary								
	sewer but should discharge to the ground outside of a building. If the roof								
	drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and					x			
	redirect the roof drains onto the ground outside the building.								
Foundation	Foundation drains are underground pipes that collect storm water from						x		
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected								
	to the sanitary sewer.								
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters						x		
1 1	basements or crawl spaces and pump it away from the house. The basic sump								
	system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.								
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary						1.		
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the					×			
	main line, shall be in a safe and functional condition and shall be free from all								
	leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and								
	specifications. (Details on back of this sheet)								
Notes:	Repairs made and inspected 5/2/2023by Highview Plumbing, Inc.								
	From home and 001 is lined as 1.01. (48.04), 40.05 (0.18.4), 45. (1.08.4)								
		From home out 22' is lined and 8' of 4" Sch 40 PVC with two 45s to 6" stub -Scott O. 5/2/2023							
	Cook of Granta Card								
Toilet Removed	d O Yes O No								
For Inspection:									
1 of Hopeottoni									
Inspectors Signature:				Date:					
Owners Signature:				Date:					
			City	Review					
☐ Corrective Action Require									
Certificate of Compliance Expires: 5/2/2033 Corrective Action Due by:						•			
Date: 5/2/2023		Signature:	7V	Willow					
5/2/2023 Name: Kellie Hoen									