2020 **SEPTIC MAINTENANCE REPORT**

Site address:64	5 Ferndale Rd North (Scott Stoltenberg)
Number of tanks:	3 Date last pumped:7-14-2020 Gallons pumped:2100
Name of pumper / ma	Intenance provider: Albin's Septic Pumping, LLC
Are tanks watertight?	: NO (please circle one)
Is the system function	ing properly? Yes (ie slow drainage, wetness in the drainfield?)
No	ific concerns or issues that you'd like to discuss with the SSTS Program Manager?
If so, please indicate b	pest time and telephone number(s) to be reached between 8 am and 4:30 pm.
Best Times	Telephone Number(s)

RETURN IN THE ENCLOSED ENVELOPE

AS SOON AS POSSIBLE

ROGER PEITSO CITY OF ORONO PO BOX 66 CRYSTAL BAY MN 55323-0066