



Date Called in	
Date Scheduled	

City Of Orono
Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	2114 Sugarwood Dr
PID:	3411823210027

Owner Information			
Name:	Kelley Woodhead		
Mailing Address: (if different from Property)			
Phone:	612-597-2257	Email:	jkwoodead@sbcglobal.net

Inspector Information			
Name:	Scott Oberaigner		
Company/ Organization	City of Orono	License number:	
Phone:		Email:	

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	X	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	X	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	X	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	X	
Notes:			
Toilet Removed For Inspection:	o Yes <input checked="" type="checkbox"/> No		

Inspectors Signature:	Date: 3/17/2022
Owners Signature:	Date:

City Review	
<input checked="" type="checkbox"/> Compliant	<input type="checkbox"/> Corrective Action Required
Certificate of Compliance Expires: 3/17/2032	Corrective Action Due by:
Date: 3/18/2022	Signature: Kellie Hoen
	Name: Kellie Hoen

CITY OF ORONO
INSPECTION NOTICE
PERMIT NO. SWP22-000012
ADDRESS 2114 Sugarwood Dr
OWNER Gary
CONTRACTOR Marvel Sewer & Drain 763 568 3590

DATE 3/14/22
TIME 1:15 PM

CODE REQUIREMENTS ARE FOR YOUR PERSONAL HEALTH AND SAFETY!

DESCRIPTION
☐ FOOTING ☐ DEMO - FINAL ☐ SEPTIC FINAL
☐ POURED WALL ☐ PLUMBING RI ☐ EXCAV/GRADING/FILLING
☐ FOUNDATION DRAIN TILE ☐ PLUMBING FINAL ☐ TREE REMOVAL
☐ LATHE ☐ MECHANICAL RI ☐ SITE INSPECTION
☐ FRAMING ☐ MECHANICAL FINAL ☐ RATED WALLS
☐ INSULATION ☐ WOOD BURNER/FIREPLACE ☐ COMPLAINT
☐ FINAL ☐ WATER HOOK-UP ☐ FOLLOW-UP
☐ AS BUILT - SURVEY ☐ SEWER HOOK-UP ☐ FOUNDATION/REMOVAL
☐ DEMO - SITE ☐ SEPTIC INSTALL

OWNER/CONTRACTOR TO MEET YOU: YES NO
COMMENTS: 2' repair where 3035 pipe meets Sch 40 pipe - This was done because of root intrusion where 3035 pipe & Sch 40 pipe meet.

WORK SATISFACTORY: PROCEED
☒ CORRECT WORK & PROCEED
☐ CORRECT WORK, CALL FOR REINSPECTION BEFORE COVERING
☐ CORRECT UNSAFE CONDITION WITHIN _____ HOURS. INSPECTOR WILL RETURN
☐ STOP ORDER POSTED. CALL INSPECTOR
☐ INSPECTION REQUIRED. CALL TO ARRANGE ACCESS.

☐ PROJECT COMPLETE
☐ ISSUE CERTIFICATE OF OCCUPANCY
_____ TEMPORARY
_____ PERMANENT
☐ PHOTO TAKEN
☐ CITATION ISSUED

Call for the next inspection 24 hours in advance. (952) 249-4600
Owner/Contractor on site: Gary
Inspector: Gary