## TASK 63408



Date Called in 4/12/2022 Date Scheduled 4/19/22 12:45 PM

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		2845 Little Orchard Way					
PID:		0911723210011					
		OI	nformation				
Name:	Anne	elie Bergerson	mormation				
Mailing Address: (if different from		Dorgeroon	CERTIFIED EXPIRES: 4/19/20 <b>3</b> 2.				
Property) Phone:	052.5	200-2129				<i></i>	
i none.	952-2	200-2129	Email: annelie.bergers	on@gma	il.com		
		Inspector	Information				
Name:		Inspector Information  Brian   Brandon					
Company/ Organization		Brian / Brand	License number:				
Phone:			Email:				
	Ι -		ection				
System Roof Drains	Stand				Pass	Fail	
	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation	Foundation drains are underground pipes that collect storm water from						
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	specific	ations. (Details on back of thi	is sheet)				
		/					
Toilet Removed For Inspection:	o Yes	₩No				77777	
Inspectors Signature:			Date: 4//9/2Z				
				1			
		City R	eview				
Compliant   Corrective Action Required					. 10 000 March 10 10 10 10 10 10 10 10 10 10 10 10 10	And a second state of 150	
Certificate of Compliance Expires: 4/19/2032   Corrective Action Due by:				•			
Date: 4/19/2022		Signature: Name: Kellie H	Kellietoen				

## Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	₹ (%
Type and Size of Service	W" PVC W" 3034
Overall Condition of Service Pipe	6000

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.							
Feet	Comment						
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration						
o Ĝ	Busement Garage 4" Cleanout						
07	3034 to PVC 40 Can't Push Carther						
13	Can't Proh Carther						
Notes:							