

## Date Called in

## City Of Orono Inspected after repairs Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	2700 Casco Point Rd.
PID:	2011723240022

Property Address:	2700 Casco Point Rd.					
PID:	2011723240022					
		Owner Information			30.000	
Name:	Dan a	Dan and Linsa Buesing				
Mailing Address:	CERTIFIED			2020		
(if different from	EXPIRES: 7/7/a			(032		
Property) Phone:	612-68	2-655-7832 Email: Tenmileskinny@aol.com			-	
11101101						
		Inspector Information				
Name:						
Company/ Organi	zation	License numb	ber:			
Phone:		Email:				
		Inspection			Τ	T
System	Stand				Pass	Fail
Roof Drains		rains and leaders Roof drains should not be connected to the ground outside of a b				
	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open					
		tions to the sanitary sewer using a non-shrink pe		l, and	X	
Farmdation		the roof drains onto the ground outside the buil				
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then					
Diams	1	pumped outside of the building. Foundation drains should not be connected X				
		to the sanitary sewer.				
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump					
		system includes drain tile, a sump pit, a sump pump, a float or switch, and a			X	
	drain l	drain line. Sump pumps should not be connected to the sanitary sewer.				
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary					
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree				\ \ \	
	root intrusion. The sanitary sewer lines shall meet the City Code standards and			rds and		
Notes:	specifi	cations. (Details on back of this sheet)				
110105.	Opened sewer service at 6" and lined 67' 8" 4".					
	Insta	lled -4' of 4" at 6" and 2 ferncos				
Toilet Removed	o Yes	s ∘ No				
For Inspection:						····
Γ						<del></del> .
~ ~ ~						
				Date:		
Owners Signature: Date:					***************************************	

	City.	Review		
Compliant		☐ Corrective Action Required		
Certificate of Compliance Expires: 7/7/2032		Corrective Action Due by:		
Date:	Signature:	Medon		
7/7/2022	Name: Kellie to	toen		