TASK 68492



 Date Called in
 10/4/2022

 Date Scheduled
 10/6/2022 2:00 PM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	755 Tonkawa Rd	
PID:	0511723330003	

	Owner	Information	i de la companya de
Name:	Juls BROWN		CERTIFIED
Mailing Address: (if different from	34177 N Ironwood Rd Scottsdale AZ, 85266		EXPIRES: 10/6/22
Property) Phone:	763-443-0768	Email:	jbrown@loveofit.com

	Inspector Information		
Name: Company/ Organization	License number:	12.17	
Phone:	Email:	7. f	1-1-1-

Creatom	Inspection Standard	Pass	Fail
System Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	7	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	X	2
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	X	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	K	
Notes:			
Toilet Removed For Inspection:	○ Yes No		

1.	
Inspectors Signature:	Date: 10 6 33
	Date:
Owners Signature:	

	City	Review
™ Compliant		☐ Corrective Action Required
Certificate of Compliance	Expires: 10/6/2032	Corrective Action Due by:
Date:	Signature:	Woloen
10/6/2022	Name: Kellik Hz	en

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Dlagge # s	A -11
Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.
Feet	This report must include a digital copy of the televising.
Example:	Comment
0 1-10	Start for 4" cleanout in NE corner of Basement
	Misaligned joint –Infiltration
0 ~	Clean
4	in operator
18' -	Clean out in oprage CAST Fron Clean out
	Close mil
80	- Can ou
281	
C119	
(OC)	
79	
	•
, 23°	
187	
(
SAD	
303	End 17: 50
Notes:	end of chmera