## TASK 66824



## City Of Overs

Date Called in 8/11/2022
Date Scheduled 8/24/2022 11:00 AM

## City Of Orono Inspected After Repair 10/20/2022 Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		2200 Bayview Pl.				
PID:		1711723440082				
NT	TCk - Is	The second secon	Information			
Name: Mailing Address: (if different from Property)		_			RTIFIED S:/0/20/2032	
Phone:	612-701-0274 Email: peanutshan@aol.com					
		Inspector	r Information			
Name:						
Company/ Organization			License number:			
Phone:			Email:			
	T		pection			
System	Standard				Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.				X	
Foundation	Foundation drains are underground pipes that collect storm water from					
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.				X	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.				Х	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)				х	
Notes:	1		····		L	<u> </u>
	Repairs done and inspected 10/20/2022  4-Inch HDPE bored from 6-inch at stree to SE corner of the home 5lb Air test for 15 minutes.  All OK -Scott O. 10/20/2022					
Toilet Removed	∘ Yes ∘ No					
For Inspection:						
Transactions Clauset				Tn		
Inspectors Signature: Owners Signature:				Date:		
Owners Signature: Date:						
		City	Review			
☐ Corrective Action Required						
Certificate of Compliance Expires: 10/20/2032						
Date: Signature: Lulle Hoin						