## Date Called in 6/5/2023

Date Scheduled 6/14/2023 1:30 PM

## City Of Orono Repairs inspected 6/21/2023 Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

KESHOK		V	r				
Property Address:		110 Chevy Chase Dr					
PID:		3611823410046					
110.		0011020410040	·				
		Owner 1	Information				
Name:				05	DIFFED		
Mailing Address: (if different from Property)					:s: <u>6/21/2</u> 033		
Phone:			Email:				
		Inspector	Information				
Name:							
Company/ Organization			License number:				
Phone:			Email:				
			pection				
System	Stand				Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation	Foundation drains are underground pipes that collect storm water from						
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	Sewer line repaired 6/21/2023. Offset joint 46' from outside cleanout by retaining wall and sewer service cracked at drop pipe at manhole. Ouverson lined sewer service-all of 6' clay tile lined Repairs and new video inspected and passed 6/21/2023						
Toilet Removed For Inspection:	o Yes	○ No					
×							
Inamaatana Ciamata				Datas			
Inspectors Signature:				Date:			
Owners Signature: Date:							
		City	Review				
City Review  ✓ Compliant □ Corrective Action Required							
Certificate of Compliance Expires: 6/21/2033   Corrective Action Due by:							
Date: Signature: Kellie Hoen							
6/21/2023 Name: Hilliation							
- July John							