



Task 76749

Date Called in 8/3/2023
Date Scheduled 8/9/2023 10:00 AM

City Of Orono
Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address: 3635 Lyric Avenue
PID: 1711723340044

Owner Information
Name: Julie Carlston Realtor -Ryan 612-702-4340
Mailing Address: PO Box 532 Agents# Mike Hall 612-968-3099
(if different from Property) Chanhassen, MN 55317
Phone: 571-299-9806 Email: jscarlston@gmail.com

Inspector Information
Name: Brian / Brandon
Company/ Organization: City of Orono License number:
Phone: Email:

Inspection table with columns: System, Standard, Pass, Fail. Rows include Roof Drains, Foundation Drains, Sump Pumps, Sewer Service Line, Notes (CERTIFIED EXPIRES: 8/9/2033), and Toilet Removed For Inspection.

Inspectors Signature: Brian / Brandon Date: 8/9/23
Owners Signature: Date:

City Review
 Compliant Corrective Action Required
Certificate of Compliance Expires: 8/9/2033 Corrective Action Due by:
Date: 8/9/2023 Signature: Kellie Hoen Name: Kellie Hoen

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.	
Feet	Comment
Example:	
0	Start for 4" cleanout in NE corner of Basement
1-10	Misaligned joint -Infiltration
0 0'	under stairs in crawl space 4" PVC cap
62'	Cast to PVC
100'	PVC to Cast
101	Main
Notes:	