

Date Called in 7/20/2022 Date Scheduled 7/27/2022 9:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		1003 Wildhurst Tr	ail			
PID:		0711723210016				
		Owner I	Information			
Name:						
Mailing Address:		CERTIFIED				
(if different from		EXPIRES: <u>// / 7 / 20</u>			203Z	
Property)						
Phone:	}		Email:			
		7	1-6			
NI	I	inspector	Information			
Name:		:	T:			
Company/ Organization			License number:			
Phone:		· · · · · · · · · · · · · · · · · · ·	Email:			
1 Hone.	I		Differi.			
		Inst	pection			
System	Standa		уссион		Pass	Fail
Roof Drains	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	· -·	should not be connected to the san	itarv	X	1 411
Roof Diams	sewer but should discharge to the ground outside of a building. If the roof				^	
			sewer, disconnect them, plug any o			
			ing a non-shrink permanent materia	al, and		
Foundation	redirect the roof drains onto the ground outside the building. Foundation drains are underground pipes that collect storm water from					
Drains	around the base of a building and into a sump basket, where it is then				X	
Diams	pumped outside of the building. Foundation drains should not be connected					
		itary sewer.				
Sump Pumps		pumps are designed to capture surface or ground water that enters			x	
		its or crawl spaces and pump it away from the house. The basic sump neludes drain tile, a sump pit, a sump pump, a float or switch, and a			_ ^	
		ine. Sump pumps should not be connected to the sanitary sewer.		, and a		
Sewer Service			(I/I) Compliance Inspection Sanita	ary	\ <u></u>	
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the				X	
21110	main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree					
			ted to partially collapsed sections on the shall meet the City Code standa			
		tions. (Details on back of t		a do dia		
Notes:			/2022 provided on 1/17/202	23		
	1 000101	Jan viaco aatoa 1777	72022 provided on 1717/202	.0		
		PP spot repair. 39' Cl	PP spot repair			
,	-Scott O. 1/17/2023					
Toilet Removed	o Yes	o No				
For Inspection:						
Inspectors Signature: Date						
Owners Signature: Date:						
		City	Review			
x☐ Compliant ☐ Corrective Action Required						
Certificate of Compliance Expires: 11/7/2032 Corrective Action Due by:						
Date:		Signature: XILLAHOLL				
1/17/2023		Name: Kellie Hoen				