## Task 82532



## Date Called in 2/9/2024 Date Scheduled 2/12/2024 1:00 PM

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1540 North Arm Drive
PID:	0811723330075

Property Address	s: 1540 North Arm Drive		-1 -9				
PID:	0811723330075						
. ,			, 191				
18		Owner	Information				
Name:	Jacob Miller						
Mailing Address: (if different from Property)				*	· ·		
Phone:	952-4	412-2850	Email: N	MARKPLINDGI	REN@YA	H00.C0	MC
	united the same of the						
		Inspector	r Information				
Name:		9	<del></del>				
Company/ Organi	zation		License nu	ımber:			
Phone:			Email:	11 / 10	1. 13. 7	4	
		11 4412	( # in i n / s				
	500 17		pection				
System	Stand					Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	baseme system	pumps are designed to capt ents or crawl spaces and pum includes drain tile, a sump pue. Sump pumps should not lessered.	p it away from t pit, a sump pum	the house. The bap, a float or swite	sic sump ch, and a	7	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:		ots in scrvice.		le, House	is a t	rear d	own
Toilet Removed For Inspection:	o Yes						
Inspectors Signatu	re: S	10 10 10 100 CON			Date:	3-12-	74
		Date:	104				
		1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1			- 11		
		City	Review				
□ Compliant			💆 Con	rective Action	Required		
Cartificate of Carr	alians -	Erminas	Compating	-4! D 1	Glich		

	City	Review	
□ Compliant		Corrective Action Required	
Certificate of Compliance Expires:		Corrective Action Due by: 05/12/2024	
Date:	Signature:	'when	
02/12/2024	Name: Kellic to	Den	

## **Service Line Inspection Details**

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.			
Foot			
Feet	Comment		
Example:			
0	Start for 4" cleanout in NE corner of Basement		
1-10	Misaligned joint –Infiltration		
0	cleanort in vertacal stact in basement		
20, 20,	>\$0/10 roots		
38, 20,	Chara tile		
2062			
13	MAIN		
138'			
136	For as wego		
Notes:			