TASK 83322



Date Called in 3/18/2024 Date Scheduled 3/22/2024 1:00 PM

City Of Orono Reinspected after repairs 4/24/2024 Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	3669 North Shore Drive	
PID:	0811723340051	

Owner Information				
Name:	Donald Heeman F	Realtor -Em	ily 612-812	-4702
Mailing Address: (if different from Property)	39349 N. 107th Way Scottsdale, AZ 85262			Realtor -Emily 612-812-4702 emilyl@cbburnet.com
Phone:	651-681-0142		Email:	dheeman@spencerfane.com

Inspector Information			
Name:			
Company/ Organization		License number:	
Phone:		Email:	

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	х	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	x	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	х	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	х	
Notes:	From center of driveway towards house, ouverson lined 29' of 4 to the cast iron pipe. From center of driveway to main, ouversor 4" to main. 40" PVC repair in driveway. Inspected and video provided 4/24/2024		32' all
Toilet Removed For Inspection:	∘ Yes ∘ No		

Inspectors Signature:	Date:
Owners Signature:	Date:

City Review				
Compliant		☐ Corrective Action Required		
Certificate of Compliance Expires: 4/24/2034		Corrective Action Due by:		
Date:	Signature: Lille Hoen			
4/24/2024	Name: Kellie Hoen			