TASK 84353



Date Called in 4/29/2024 Date Scheduled 4/30/2024 1:00 PM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

TOIL	int of Sale Sanitary Sewer Service 1&1 Comphance Inspection P	OTT		
Property Address:	: 1610 Shadywood Road			
PID:	1711723210010			
			1.7	
	Owner Information			
Name:	Gail Rogers Contact: Wendy Olson-Slepicka			
Mailing Address: (if different from Property)			_	
Phone:	612-695-3815 Email: yellowrosemn@hotma	ail.com		
	Inspector Information			
Name:	ization License number:			
Company/ Organi	Zation License number.			
Phone:	Email:			
		17	r Principal	
	Inspection		T	
System	Standard	Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and			
D 1.1	redirect the roof drains onto the ground outside the building.			
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected	_	-	
Comp Domes	to the sanitary sewer. Sump pumps are designed to capture surface or ground water that enter	·e		
Sump Pumps	basements or crawl spaces and pump it away from the house. The basic sum system includes drain tile, a sump pit, a sump pump, a float or switch, and drain line. Sump pumps should not be connected to the sanitary sewer.	p ,	7 9 1	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from a leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards ar specifications. (Details on back of this sheet)	11 >	124	
Notes:	bpourround (2 classes on a second property)		- 64	
Toilet Removed	o Yes No	J. 1	* *	
For Inspection:		*		
7				
		1.3.	3.1	
inspectors signature: 9-011 / 010(1)			वप	
Owners Signature: Date:				
City Davious				
City Review Compliant Corrective Action Required				
Compliant Certificate of Compliance Expires: 4/30/2034/ Corrective Action Required Corrective Action Due by:				
Date: Signature: Kellic Joen Name: Kellic Don				
	, , , , , , , ,			

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please no	te all connections, fittings, points of concern on service line including infiltration, tree root,		
	cracks, misaligned joints, etc. This report must include a digital copy of the televising.		
Feet	Comment		
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration		
0	•		
FORS			
CAST			
61'	Cleanant		
71'	PVC to liner 45° to cost		
81),	main -		
Notes:	No defient cies		