Task 82532



Date Called in 2/9/2024 Date Scheduled 2/12/2024 1:00 PM

City Of Orono City Of Orono Inspected After Repairs 7/17/2024 Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		1540 North Arm Drive				
PID:		0811723330075				
115.						
		Owner In	nformation			
Name: Jacob Miller						
Mailing Address: (if different from Property)						
Phone:	952-412-2850 Email: MARKPLINDGREN@YAHOO.COM					
		Inspector	Information			
Name:						
Company/ Organi	zation	License number:				
Phone:			Email:			
	l a		ection			I
System	Standa		-11.1 4 1 4 - 4 4 - 4 1	:4	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.				×	
Foundation	Foundation drains are underground pipes that collect storm water from					
Drains	around the base of a building and into a sump basket, where it is then				X	
	pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.					
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.				×	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)				×	
Notes:	76' of 4" Cipp and 3' of 6" to main. Video provided by Brothers Underground 8/1/2024 -Scott O					
Toilet Removed O Yes O No For Inspection:						
D.4						
Inspectors Signature: Date:						
Owners Signature: Date:						
		City F	Review			
Compliant Corrective Action Required						
Certificate of Compliance Expires: 7/17/2034. Corrective Action Due by:						
Date: Signature: White Hour						
8/1/2024 Name: Kellic Hoen						