

Date Called in 10/2/2024 Date Scheduled 10/7/2024 8:30 AM

City Of Orono reinspected after repairs 10/28/2024 Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	3580 Livingston Ave
PID:	1711723430035

Owner Information				
Name:	West Hennepin Affordable Housing Land Trust			
Mailing Address: (if different from Property)	5100 Thimsen Ave., Suite 120 Minnetonka, MN 55345			
Phone:	952-224-2853	Email:	doris@homeswithinreach.org	
i none.	002 22 1 2000	Lillaii.	dona@nomeswithmeach.org	

Inspector Information			
Name:			
Company/ Organization		License number:	
Phone:		Email:	

	Inspection		
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	х	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	х	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	x	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	x	
Notes:	Sewer Lined 25' from main to house. Repair inspected an provided 10/28/2024	d video)
Toilet Removed For Inspection:	∘ Yes ∘ No		

Inspectors Signature:	Date:
Owners Signature:	Date:

City Review				
Compliant		☐ Corrective Action Required		
Certificate of Compliance Expires: 10/28/2034		Corrective Action Due by:		
Date: Signature:		lleHour		
10/29/20204	Name: Kellie Hoen			