

Date Called in			
Date Scheduled	5	7	25

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1045 Loma Linda Avenue
PID:	0811723230022

Property Address:		1045 Loma Linda Avenu	ie			
PID:		0811723230022				
						~
		Owner In	nformation		***************************************	
Name:	Kris	sti Osterberg	A VA AAAAAA VAA			******
Mailing Address: (if different from Property)			13			-
Phone:	952-	472-1873	Email: Osterberg 111@	ற்சாail.co		
- William Co.	<u> </u>		Linear, Source	Rimanier	111	
Name;		Inspector I	Information			
Company/ Organiz		City of Orono	T	1		
Company/ Organiz	zation _j	City of Orono License number:				
Phone:		952-249-4686 612-916-1685	Email;			
		736-647-4000 014 770 1000	Eman,	L		
		Inspe	ection			
System	Stand		VIOII		Pass	Fail
Roof Drains	Roof di	rains and leaders Roof drains sh	hould not be connected to the s	anitary	Гива	Pau
	sewer b	but should discharge to the grou	and outside of a building. If the	roof	/	
	drains a	are connected to the sanitary sections to the sanitary sewer using	wer, disconnect them, plug any	open	:/	
	redirec'	t the roof drains onto the ground	g a non-surms permanent mate d outside the building.	rtal, ano		
Foundation	Founda	ation drains are underground pir	pes that collect storm water from	m		-
Drains	around	the base of a building and into	a sump basket, where it is then	1	/	
1		d outside of the building. Found sanitary sewer.	dation drains should not be con-	nected	/	
Sump Pumps	Sump p	pumps are designed to capture	e surface or ground water th	at enters	 	-
	baseme	ents or crawl spaces and pump is	it away from the house. The ba	sic sump	1/	
	drain li	includes drain tile, a sump pit, ne. Sump pumps should not be	, a sump pump, a float or switch	ch, and a		
Sewer Service	Sanitary	y Sewer Inflow & Infiltration (I	I/I) Compliance Inspection San	nitary		
Line	Sewer I	Lines. All sanitary sewer lines s	serving Property, from the hous	se to the		
	main lu	ine, shall be in a safe and function failures including but not limited	onal condition and shall be free	from all		
	root int	tailures including but not limited trusion. The sanitary sewer lines	d to partially comapsed sections shall meet the City Code stan	or tree		
		cations. (Details on back of this		Jan Co		1
Notes:					R	1
		Root Intrusion	Λ			
		1001111				
Toilet Removed	o Yes	1 11.				·····
Toilet Removed O Yes No For Inspection:						
For hispection;						
	,- 			-4		
Inspectors Signatur	-a. 14	o. no		Dotar	7 7 7 7	٠, ٠
Owners Signature:		That he		Date: 9	2.4.	7-
Owners Digitalia.	7	wall walled		Date.	2-1-	פעט
4.4.4		City Re	aviau			
☐ Compliant			Corrective Action	Dannired		
Certificate of Comp	nliance	Eunirea (Corrective Action Due by:		- 55	
Date:	manice	Signature: / Signature:		P = 1	- 01.	
Date: <_9_0	><	Signature.	T SULLES		*************	

Owners Signature:	the the	Dero	- Address to the second	Date: 6-7-25
79,	,			
		City	Review	
☐ Compliant			∇ Corrective Action R	equired
Certificate of Compliance E	xpires:		Corrective Action Due by:	5-7-25
Date:	Signature:	- 74cm	to sum	
J-7-&5	Name:	Heat	her Suifeig	

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	1
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising. Feet Comment Example: 0 Start for 4" cleanout in NE corner of Basement 1-10 Misaligned joint -Infiltration 0 START AT STACK, C.O. IN Mech. Room SO' ONTBILL C.O.

135' ROST

WO Y'CAST 96" PLASTIC

168 MAIN Notes: