

CITY OF ORONO

INSPECTION NOTICE

PERMIT NO. SWP25-000029

CALLED IN

SCHEDULED

COMPLETED

DATE

TIME

7/11/259amADDRESS 3271 Casco Circle

OWNER

TELEPHONE NO.

612-919-4343

CONTRACTOR

DSM Excavating - John

DESCRIPTION

Sewer Repair + Sewer/Water☐ FOOTING☐ POURED WALL☐ FOUNDATION DRAIN TILE☐ LATHE☐ FRAMING☐ INSULATION☐ FINAL☐ AS BUILT - SURVEY☐ DEMO - SITE☐ DEMO - FINAL☐ PLUMBING RI☐ PLUMBING FINAL☐ MECHANICAL RI☐ MECHANICAL FINAL☐ WOOD BURNER/FIREPLACE☐ WATER HOOK-UP☐ SEWER HOOK-UP☐ SEPTIC INSTALL☐ SEPTIC FINAL☐ EXCAV/GRADING/FILLING☐ TREE REMOVAL☐ SITE INSPECTION☐ RATED WALLS☐ COMPLAINT☐ FOLLOW-UP☐ FOUNDATION/REMOVALOWNER/CONTRACTOR TO MEET YOU: ☐ YES ☐ NOCOMMENTS: Sewer task # 962624" sch 40 PVC - Roughly 50' With 4" Cleanout  
Connected to 4" clay with Strong Back Fernco's  
Clay portion has been linedWater task # 962633/4" at Curb stop to 1" IPS Poly☐ WORK SATISFACTORY: PROCEED☐ CORRECT WORK & PROCEED☐ CORRECT WORK, CALL FOR REINSPECTION  
BEFORE COVERING☐ CORRECT UNSAFE CONDITION WITHIN \_\_\_\_\_ HOURS.  
INSPECTOR WILL RETURN☐ STOP ORDER POSTED. CALL INSPECTOR☐ INSPECTION REQUIRED. CALL TO ARRANGE ACCESS.☐ PROJECT COMPLETE☐ ISSUE CERTIFICATE OF OCCUPANCY

\_\_\_\_\_ TEMPORARY

\_\_\_\_\_ PERMANENT

☐ PHOTO TAKEN☐ CITATION ISSUED

Call for the next inspection 24 hours in advance. (952) 249-4600

Owner/Contractor on site: \_\_\_\_\_

Inspector: \_\_\_\_\_