



Date Called in	
Date Scheduled	6-18-25

**City Of Orono**  
**Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form**

Property Address:	3745 TOGO RD ORONO, MN
PID:	17-17-23-31-0046

Owner Information	
Name:	RICKY TUCKER
Mailing Address: (if different from Property)	3745 TOGO RD ORONO MN
Phone:	612 412 3045
Email:	

Inspector Information	
Name:	JIMMY NELSON - City of Orono
Company/ Organization	Kevin Gillis - Johns Sewer + Drains
License number:	
Phone:	612-756-7394
Email:	Kgillis@johnsdrains.com

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	✓	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.	✓	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.	✓	
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	✓	
Notes:	Video from Johns Sewer + Drains was reviewed by Jimmy Nelson, Supervisor and from		

Inspectors Signature:	Date: 6/18/25
Owners signature:	Date: 6/18/25

City Review	
<input checked="" type="checkbox"/> Compliant	<input type="checkbox"/> Corrective Action Required
Certificate of Compliance Expires: 6-18-2035	Corrective Action Due by:
Date: 6-18-25	Signature:
	Name: Heather Smicja

**Service Line Inspection Details**

Weather Conditions:	cloudy
Approximate Depth of Service	5
Type and Size of Service	4 3/4 INCH
Overall Condition of Service Pipe	Good

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.	
Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint - Infiltration
0 0-84' 84-104' Street @ 105'	4" Cast iron from cleanout in basement 6" composite pipe.
Notes:	