

## 2020 SEPTIC MAINTENANCE REPORT

Site address: 470 Orchard Park Rd ( Jonathan & Catherine Norris )

Number of tanks: 2 Date last pumped: 7-12-2020 Gallons pumped: 2350

Name of pumper / maintenance provider: Albin's Septic Pumping, LLC

Are tanks watertight?:

☒ YES

NO

(please circle one)

Is the system functioning properly? Yes  
(ie slow drainage, wetness in the drainfield?)

Do you have any specific concerns or issues that you'd like to discuss with the SSTS Program Manager?

No

If so, please indicate best time and telephone number(s) to be reached between 8 am and 4:30 pm.

Best Times

Telephone Number(s)

**RETURN IN THE ENCLOSED ENVELOPE  
AS SOON AS POSSIBLE**

**ROGER PEITSO  
CITY OF ORONO  
PO BOX 66  
CRYSTAL BAY MN 55323-0066**