
Date Called in Date Called in 4/4/2022
Date Scheduled 4/5/22

1:30



T OII	11 01 54	ale Salitally Sewel Selvic	e 1821 Computance inspecu	OM TOIM	.1		
Property Address:		1925 Country Club Road					
PID:		2711823430002					
		~ ·					
Name:	Clop C	Owner In Fredeen	formation				
Mailing Address:	Gien G	riedeen		OFDICE	·n		
(if different from Property)				CERTIFIED XPIRES: <u>4/5/203</u> 2			
Phone:	(H) 95	4-473-3289	Email: glfredeen@gmail.co	om			
	San and the San and the San						
3.7			nformation				
Name:	4!	Justin Brandon					
Company/ Organization		City of Orono	License number:				
Phone:			Email:				
			•				
<u> </u>	a,		ection		D		
System	Stand		hould not be connected to the san	:t	Pass	Fail	
Roof Drains			and outside of a building. If the re				
			wer, disconnect them, plug any o		/		
			g a non-shrink permanent materi	al, and	V		
Foundation		t the roof drains onto the groun	pes that collect storm water from				
Drains	around the base of a building and into a sump basket, where it is then						
2.4	to the s	anitary sewer.	dation drains should not be conne		V,		
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump						
			, a sump pump, a float or switch		1/		
	drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the						
Line	main line, shall be in a safe and functional condition and shall be free from all						
	leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and						
		rusion. The santary sewer fine cations. (Details on back of thi		iras ana			
Notes:	-1						
		/					
m-11-4 D 1	- 37	1.61					
Toilet Removed For Inspection:	o Yes	Ø No					
ror inspection:							
Inspectors Signature: Date: 7/3					7/4/	15	
Owners Signature:				Date:			
City Review							
Compliant Corrective Action Required							
Certificate of Compliance Expires: 4/5/2032 Corrective Action Due by:							
Date: Signature: Killetoen							
4/5/2022 Name: Kellie Hoen							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root,						
cracks, misaligned joints, etc. This report must include a digital copy of the televising.						
Feet	Comment					
Example:						
0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration					
1-10						
0	west side of nowix is from foundation 4" Cleanout					
2	They have by thouse is thought to the state of Close					
O	$\mathcal{M}_{\mathcal{N}_{N}}}}}}}}}}$					
the	A Dan					
de	Marko					
>	$\sim \Lambda_{\sim}$					
(15)	MICH					
V						
Nistan						
Notes:						