

Date Called in	
Date Scheduled	

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1375 Park Drive
PID:	0711723410079

Froperty Address.		1375 Park Drive						
PID:		0711723410079						
			Owner Inf	formation	ì			
Name:	Mike I	Mike Rosolanka						
Mailing Address:						CERTIFIE		
(if different from	1				EXI	PIRES: <u>5/3</u>	3/2032	
Property)						***************************************		
Phone:	612-40	612-408-4823 Email: mike@rosolanka.com						
			Inspector I	nformatic	n			
Name:								
Company/ Organi	zation			License number:				
D1				m. 11.				
Phone:				Email:				
			<b>.</b>	.,.				
<u> </u>	I a.	7 7	Inspe	cuon			D	T 101 - 11
System	Stand		D - 6 4 - ! 1	1 1.		14	Pass	Fail
Roof Drains	1				e connected to the sa of a building. If the	•		
					nnect them, plug any			
					ink permanent mate	rial, and		
		t the roof drains						
Foundation					lect storm water from			
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected							
	to the sanitary sewer.							
Sump Pumps		Sump pumps are designed to capture surface or ground water that enters						
• •	basements or crawl spaces and pump it away from the house. The basic sump							
	system includes drain tile, a sump pit, a sump pump, a float or switch, and a							
Sewer Service		drain line. Sump pumps should not be connected to the sanitary sewer.  Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary						
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all							
Line								
	leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)							
Notes:	Spot Repair done from 67.2ft to 69.2ft and 24.7ft to 29.7ft Video reviewed by Scott 5/10/2022							
:	DOUR FEMILY CHAIR CLAME A 17 THE DOUBLE THE TOTAL THE TOTAL THE					1.177		
	Video reviewed by Scott 5/10/2022							
	AICH		,	- ( • /-				
Toilet Removed	o Yes	o No						
For Inspection:								
•	•							
Inspectors Signature:						Date:		
					Date:			
estantian technologica at a tradition of the destantial and the destantial as			\$2.6585566.05565666655_165656667_1656	Carlos Armatechnic Interna		and the state of t	a los delas legacia di consu	

	City	Review		
▼ Compliant		☐ Corrective Action Required		
Certificate of Compliance Expires: 5/3/2032		Corrective Action Due by:		
Date: 5/10/2022	Signature:	Methoen		
	Name: Kellie Hoen			