TASK 65165



Date Called in 6/1/2022

Date Scheduled 6/7/2022 1:00 PM

Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form 9/13/2022 1:00 PM

Wilhor	01 81	, ,	range and the contract of the		RUS	andi	
Property Address:		4655 Tonkaview Ln					
PID:		0711723320064					
			er Information				
Name:	John	Larson					
Mailing Address: (if different from	CERTIFIED				000		
Property)		EXPIRES: <u>4/13/2</u> 032					
Phone:	612-618-5912 Email: John@Larsonlawnscape.com						
		- ·			504500000000		
N I		Inspec	tor Information				
Name: Company/ Organization		31144/10	License number:				
Company/ Organizatio		(Electise number.				
Phone:			Email:				
			nspection		-1		
System	Stand		nins should not be connected to the sa		Pass /	Fail	
Roof Drains			e ground outside of a building. If the i				
	drains a	are connected to the sanita	ary sewer, disconnect them, plug any	open		1	
x_{p}			r using a non-shrink permanent mater	ial, and		ŧ	
Foundation	redirect the roof drains onto the ground outside the building. Foundation drains are underground pipes that collect storm water from						
Drains		_	d into a sump basket, where it is then			! 	
'		_	Foundation drains should not be conn	ected	J = J	<i>(</i>	
Sump Pumps		to the sanitary sewer. Sump pumps are designed to capture surface or ground water that enters					
. 1			ump it away from the house. The bas			ı	
			np pit, a sump pump, a float or switch of be connected to the sanitary sewer.		\vee	ı	
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary						
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all						
			limited to partially collapsed sections		/		
	root int	rusion. The sanitary sewer	r lines shall meet the City Code stand		<i>'</i>		
Notes:	specific	ations. (Details on back of	of this sheet)				
rioles.		•					
		<u> </u>					
Toilet Removed	o Yes	A No					
For Inspection:							
			7				
Inspectors Signatu	ıre:	ASO	}	Date: 0	-" 2	127	
Owners Signature:				Date:		100	
9 , , 11012 218110111				_1			
		Ci	ity Review				
Compliant Corrective Action Required							
Certificate of Compliance Expires: 6/13/2032 Corrective Action Due by:							
Date: Signature: Kill elchoeu							
10/13/2022 Name: Killie Hoen							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	·
Type and Size of Service	
Overall Condition of Service Pipe	·

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.						
This report must include a digital copy of the televising.						
Feet	Comment					
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration					
0 0	Bushment willy Down 3' Cleanon					
36	Vin Pipe Vin Pipe Wi pro to 6" Trus Main					
36 63'	1108:02					
93'	My Drofo C 11mg					
120	Main					
Notes:						