## TASK 65417



Date Called in 6/13/2022 Date Scheduled 6/15/2022 10:00 AM

City Of Orono
Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form & WWW 4 | 2 | 2022

1.30 AW

1.30 AW

Property Address:		605 Park Lane					
PID:		0611723410049					
		Owner In	formation				
Name:	Bruce Meyer						
Mailing Address: (if different from Property)		CERTIFIED EXPIRES: 6/21/2			<b>D</b> 21/2032	•	
Phone:	952-2	37-3786	Email:  bbruceblm2@aol.co	om			
						Date Company of the C	
Inspector Information							
Name:		Brian/ Bratak					
Company/ Organization		City of drono	License number:				
Phone:			Email:				
	ales de la constant						
		Inspe	ction				
System	Stand				Pass	Fail	
Roof Drains	sewer drains connec	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.					
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	baseme system	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:						·	
Toilet Removed O Yes No For Inspection:							
			4				
1				Date:	-7 -7 -7		
		——————————————————————————————————————	•		Sangara San San San	1	
City Review							
Compliant   Corrective Action Required							
Certificate of Compliance Expires: 6/2//2032   Corrective Action Due by:							
Date: Signature: Kille Hoen Name: Kille Hoen							

## **Service Line Inspection Details**

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	M" GEST M" PVC
Overall Condition of Service Pipe	Good

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.							
Feet	Comment						
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration						
9	Busement willy Room East Corner 4" Court						
16	Cost to PIC						
<i>ال</i> ا	Main						
Notes:							