TASK 67634



 Date Called in
 9/1/2022

 Date Scheduled
 9/9/2022 10:30 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	2475 Dunwoody	2475 Dunwoody Ave				
PID:	2011723220014	2011723220014				
		€i				
3.		Information				
Name:	Scott Landgraf					
Mailing Address: (if different from						
Property)						
Phone:	651-955-9663	Email: So	cott@izzamanufactu	ring.com	ı	
		*				
N	Inspecto	r Information				
Name:		1.	1			
Company/ Organiz	zation	License nun	aber:			
Phone:		Email:				
	Ins	pection			100.00	
System	Standard			Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof					
	drains are connected to the sanitary					
	connections to the sanitary sewer us	sing a non-shrink p	permanent material, and			
Foundation	redirect the roof drains onto the gro Foundation drains are underground			 '		
Proundation Drains	around the base of a building and in					
Diams	bumped outside of the building. Foundation drains should not be connected					
	to the sanitary sewer.			<u> </u>	<u> </u>	
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump					
	system includes drain tile, a sump					
	drain line. Sump pumps should not			Ů		
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines, All conitors cover lines serving Property from the house to the					
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all			1		
	leaks, failures including but not lim				V	
	root intrusion. The sanitary sewer li specifications. (Details on back of		City Code standards and			
Notes:	specifications. (Details on back of	uns sneet)		.l	<u> </u>	
m u . n						
Toilet Removed	o Yes No					
For Inspection:						
	^					
Inspectors Signatu	Inspectors Signature: Date:			9.0		
Owners Signature: Date						
3 (111013 3 1 <u>B</u> 110101 4 1	· · · · · · · · · · · · · · · · · · ·			<u>. </u>		
City Review						
☐ Compliant						
Certificate of Compliance Expires: Corrective Action Due by: 12/9/2022						
Date: Signature: Flillecheen						
9/9/2022	Name: Killia	Horan				

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root,				
cracks, misaligned joints, etc. This report must include a digital copy of the televising.				
Feet	Comment			
Example:				
0	Start for 4" cleanout in NE corner of Basement			
1-10	Misaligned joint —Infiltration			
0	Cast Iron clamout Tel S.E. corner utility room			
	S.E. corner utility room			
	·			
:				
53'	4" cast complete blockage -voots			
Notes:	,			
-				