TASK 66816 -



Date: 10/6/2022

8/9/2022 Date Called in

Date Scheduled 8/11/2022 10 AM

RISCHARDED FORM

Inspection Form

City Of Orono

Poin	t of Sa	ale Sanitary Sewer	Servic	ee 1&1 Compliance Inspe	ecuo	n Forn	.1	
Property Address:		2697 Ethel Ave	nue			¥ 2-		
PID:		2011723240045						
			wner In	formation				
Name:	Marc Cohen CERTIFIED							
Mailing Address: (if different from Property)	A	EXPIRES:					10/6/2	032
Phone:	612-558-2108 Email: mwilliam668@gmail.com							
		Insj	pector I	nformation				
Name:				License number:	\top			
Company/ Organization				License number.		/		
Phone:		1 14		Email:	1	- £		
			Į.					
			Insp	ection			Desa	Fail
System	Stand	lard		1 11 11		-0477	Pass	Fall
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.							
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.							
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.							
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)							
Notes:								
Toilet Removed For Inspection:	o Ye	s No	A 1	1, 11 A	* >	,		
			-	2				
		to a late				Data	1-1-	3
Inspectors Signatu		30/1000714			Date:	10		
Owners Signature: Date:								
			G*.	n :				
~			City	Review	D	o avvine	1	
Compliant								
Certificate of Compliance Expires: 10/0/2032 Corrective Action Due by:								
Date: Signature: Killfolkern								
10/6/2022 Name: Kellie Horn								

Service Line Inspection Details

XXX .1 .0 .11.1	
Weather Conditions:	
Approximate Depth of Service	
^	
Type and Size of Service	
Overall Condition of Service Pipe	
*	

Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.
Feet	Comment Comment
Example:	Comment
0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration
0	Clean of in basement - CAST From
717	CAST Fron
85 Abs	nAin
Notes:	All 9000