

Date Called in Date Scheduled

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:	1920 Fagerness Point Road
PID:	1711723230031

	Owner Information	
Name:		
Mailing Address: (if different from Property)		CERTIFIED EXPIRES:11112027
Phone:	Email:	

	Inspector Information	
Name:		
Company/ Organization	License number:	
Phone:	Email:	

Inspection			
System	Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.		
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.		
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)		
Notes:	Sewer connection for the new home was connected a on 11/17/2017. Compliancy is valid for 10 years from t		
Toilet Removed For Inspection:	∘ Yes ∘ No		

Inspectors Signature:	Date:
Owners Signature:	Date:

City Review			
🛛 Compliant		Corrective Action Required	
Certificate of Compliance E	xpires:11/17/2027	Corrective Action Due by:	
Date:	Signature: X	Utom.	
10/11/2022	Name: Kellie Hoen	•	

CITY OF ORONO INSPECTION NOTICE PERMIT NO	CALLED IN SCHEDULED COMPLETED 970 FQC	DATE 1VIG(17 PT	TIME <u>230</u> Rd
		HONE NO. 62	- 868 - 8072
OWNER	ICA Plush	HUNE NU. U V	(Rin)
	Fluind	/	
DESCRIPTION	Sever	hookup	
FOOTING POURED WALL FOUNDATION DRAIN TILE LATHE FRAMING INSULATION FINAL AS BUILT - SURVEY DEMO - SITE OWNER/CONTRACTOR TO MEET COMMENTS: 5/b All wK J'' Sch 40 Pipe	> /	EPLACE COMPL FOLLO FOLLO FOLLO	/GRADING/FILLING REMOVAL ISPECTION WALLS LAINT W-UP DATION/REMOVAL
WORK SATISFACTORY: PROCI CORRECT WORK & PROCEED CORRECT WORK, CALL FOR F BEFORE COVERING CORRECT UNSAFE CONDITION INSPECTOR WILL RETUR STOP ORDER POSTED. CALL F INSPECTION REQUIRED. CALL Call for the next in Owner/Contractor on site Inspector:	REINSPECTION ON WITHIN HOURS. IN INSPECTOR L TO ARRANGE ACCESS. Inspection 24 hours	PHOTO TAKEN CITATION ISSUED	TE OF OCCUPANCY DRARY ANENT
	()		
White Copy/Inspec	ctor's File	Canary Copy/Site N	lotice