

TASK 70199

Date Called in 12/13/2022
Date Scheduled 12/15/22 9:00 am

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

	The second secon	
Property Address:	3065 Jamestown Rd	1
PID:	2811823330008	

	Owner In	formation	
Name:	Paige Von Bank		
Mailing Address: (if different from Property)	3070 independence Rd Independence, MN 55359		CERTIFIED EXPIRES: 12/15/2032
Phone:	612-385-5562	Email:	povonbank@gmail.com
	Inspector		

Inspector Information		
Name:		
Company/ Organization	License number:	
Phone:	Email:	

System	Inspection Standard	Pass	Fail
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.	4	
Foundation Drains	Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.		
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.		
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)	1	
Notes:	Cleun out next to Zurance		
Toilet Removed For Inspection:	o Yes No		

	1
Inspectors Signature: Scott / Scandar)	Date: / 2 / 5 10/0
Owners Signature:	Date:

	City 1	Review	
		☐ Corrective Action Required	
Certificate of Compliance Expires: 12/15/2032		Corrective Action Due by:	
Date: Signature: Killu Heen			
12/15/2022	Name: Kellie Hoen		

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	A. DIC
Overall Condition of Service Pipe	4004

110450 110	te all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.
Feet	Comment
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration
0	^
33'-	Inside to out side-clemant
E-1 TV	$9n\xi$
Notes:	A11 0K