TASK 72135



_..

 Date Called in
 2/3/2023

 Date Scheduled
 2/6/2023

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

10 AM

		2745 ETHEL AVE					
PID:		2011723240016					
		Owner I	nformation				
Name:	Amber Peifer						
Mailing Address: (if different from Property)							
Phone:	612-7	702-7420	Email: amp	peifer@gr	nail.com		
			Information				
Name:		Brian //3ra	ndon				
Company/ Organization		Brian /13rd	License number:				
		City Of Uron)				
Phone:			Email:				
_			ection		T =		
System	Stand				Pass	Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation		tion drains are underground p		ater from		}	
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.						
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary						
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:	Бросия	\					
Toilet Removed	o Yes	φ.Mo					
For Inspection:				***************************************			
		,,,,,,					
			A			, , ,	
Inspectors Signature:		Date:			[3]		
Owners Signature:			I	Date:	***************************************		
		City	Review/	000 0000			
☐ Compliant							
Certificate of Compliance Expires:		Expires:	Corrective Action Due by: 5/6/2023				
Date; Signature: Killichloen							
2/6/2023		Name: Kelliette					

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	4" Clay 4" Cast 6" Trus
Overall Condition of Service Pipe	Bad

Please no	ote all connections, fittings, points of concern on service line including infiltration, tree root,							
cracks, misaligned joints, etc.								
	This report must include a digital copy of the televising.							
Feet	Comment							
Example: 0	Start for 4" cleanout in NE corner of Basement							
1-10	Misaligned joint –Infiltration							
0	4" cleanant in Basement Next to water heater and							
o`	19, Clerrand in Deal Mond in the content of the							
	Sink							
	Clay to Cost Roods at Soint Roods at Soint Roods at Soint Roods at Soint							
	1 to COO,							
11	() L							
	2 Joins							
	Roots V							
3	1 / Nich							
J	a de ot source							
27	Kons							
ا ي (in the Solvet							
(6)	Roots Con to Print							
50	Roots at Connection							
公分分分分分	Roots at Soint Roots at Soint O'Trust to Clay Roots at Connection Point Wain							
52	("\not ")							
77	V							
*								
a	Main							
Notes:								
inotes;								