

4/24/2023 5/1/2023 1:00 PM Date Called in
Date Scheduled

## City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Г								
Property Address:		661 Sandstone Circle						
PID:		3311823110035						
			Owner In	nformation				
Name:	Jessi	ca E Freeland						
Mailing Address:						CERTIFIED		
(if different from	EXP			RES:5/1/	2033			
Property) Phone:	612-251-5884 Email: jessica@avenuerealtyr				nn com			
1 Hone.	012-2	-01-000-		Eman:   Jessiea@avene	Cicaltyi	1111.00111		
		Ins	spector T	Information				
Name:		1110	spector 1	an on manon				
Company/ Organization				License number:				
Company/ Organization				Breense number.				
Phone:				Email:				
				1				
			Inspe	ection				
System	Stand	ard				Pass	Fail	
Roof Drains				should not be connected to the sa				
	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open							
				ewer, disconnect them, pitig any o				
				nd outside the building.	iai, aiia	X		
Foundation	Founda	tion drains are under	ground pi	ipes that collect storm water fron	1			
Drains				a sump basket, where it is then				
		mped outside of the building. Foundation drains should not be connected			ソ			
Sump Pumps	to the sanitary sewer.  Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump							
Sump rumps								
	system includes drain tile, a sump pit, a sump pump, a float or switch, and a					×		
				connected to the sanitary sewer.			ļ	
	wer Service  Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary  Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all							
Line						\ \ \		
	leaks, fa	ailures including but	not limite	ed to partially collapsed sections	or tree	/		
				es shall meet the City Code stand	ards and			
Notes:	specific	ations. (Details on b	back of thi	is sneet)		1	<u> </u>	
110105.		***						
	BD 0 009							
Toilet Removed	o Yes	⊗ No						
For Inspection:		<b>^</b>						
<u> </u>	L							
Inspectors Signatu	Inspectors Signature: 5cott Brandon Date:					5-1-23		
					Date:			
			City R	Review				
Compliant								
Certificate of Compliance Expires: 5/1/2033   Corrective Action Due by:								
Date: Signature: Killethacu								
5/1/2023	ζ	Name: Kell	No Ho	OFN				

## Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	4" PVC 56/240
Overall Condition of Service Pipe	Cool

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.				
Feet	Comment			
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration			
0	"Cleanost in wall in Theatre room			
	Prc-1"			
27)	MAIN - 4" PVC SCL NO			
Notes:				
	600p //A			