

Date Called in 7/24/2023
Date Scheduled 7/25/2023 1:00 PM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		460 E Long Lake Rd					
PID:		3511823140003					
Owner Information							
Name:	David	David and Elizabeth Johnson					
Mailing Address: (if different from Property)	*		i				
Phone:	e: 952-949-4929 or 949-929-1351 Email: basketgirl19@aol.com						
		Inspector Information					
Name:		Brian / Brandon					
Company/ Organization		City of Orono License number:					
Phone: Email:					1		
	5777756	Ť	•			1.7	
G 4	Inspection				D	T7-21	
System Roof Drains		Standard Pass Roof drains and leaders Roof drains should not be connected to the sanitary				Fail	
Roof Drains	sewer l drains	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.					
Foundation	Founda	Foundation drains are underground pipes that collect storm water from					
Drains		around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected					
		to the sanitary sewer.					
Sump Pumps	baseme system drain li	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					
Sewer Service Line	Sewer: main li leaks, f root int	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					
Notes:	CERTIFIED EXPIRES: 7 25 2033						
7D 11 (D 1	***			-		- 1	
Toilet Removed	○ Yes ○ No						
For Inspection:						-	
Inspectors Signature: The Mrs. Date:			Date:	7/73-	7-		
Owners Signature:		Date:		1/60/60			
Owners Signature:							
/ City Review							
Compliant Corrective Action Required							
Certificate of Compliance Expires: 7 25 2033 Corrective Action Due by:							
Date: Signature: Allethen							
1/15/2023 Name: Vallie Hoen							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.						
Feet	Comment					
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration					
0	I East side of house against foundation 4" PVC					
O,						
	·					
M3,	Tank					
Notes:						