TASK 76470



Date Called in Date Scheduled 7 31 23 8:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		2640 Kelly Ave					
PID:		2011723140006					
		2011/20110000					
		Owner Information					
Name: John Volkmar							
Mailing Address:							
(if different from							
Property)	040.5	20,000			As		
Phone:	612-5	08-2006 Email: johnvolkmar@	sprintmail.	com			
		Inspector Information	3200 F. 194				
Name:		mspector information					
Company/ Organiz	zation	License number:					
Company, Organiz	Lation	Dicense number.					
Phone:		Email:			(
	'	•			300		
		Inspection	, NAV . E	1000			
System	Stand		. /	Pass	Fail		
Roof Drains		rains and leaders Roof drains should not be connected to the		0			
	sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open						
		tions to the sanitary sewer using a non-shrink permanent ma		1 V			
4	redirect	t the roof drains onto the ground outside the building.		ļ ,			
Foundation	Foundation drains are underground pipes that collect storm water from						
Drains		the base of a building and into a sump bask t, where it is the doutside of the building. Foundation drains should not be contained to the building.		11/			
		anitary sewer.	mected				
Sump Pumps		pumps are designed to capture surface or ground water	that enters				
		nts or crawl spaces and pump it away from the house. The					
		includes drain tile, a sump pit, a sump pump, a float or sw		V			
Sewer Service		ne. Sump pumps should not be connected to the sanitary sev y Sewer Inflow & Infiltration (I/I) Compliance Inspection S		 			
Line	Sewer Lines. All sanitary sewer lines serving Property, from the house to the						
Line	main line, shall be in a safe and functional condition and shall be free from all						
~		ailures including but not limited to partially collapsed section		\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \			
		rusion. The sanitary sewer lines shall meet the City Code states ations. (Details on back of this sheet)	indards and				
Notes:	Брагана				7		
	CERTIFIED EXPIRES: 7/3/2033						
		EXPIRE	s: 1131203	3	7		
			, , , , , ,		~		
Toilet Removed	o Yes	⊌ No					
For Inspection:		5)					
T					10-		
Inspectors Signatur	re:	200 Min	Date:	//31/	23		
Owners Signature: Date:							
		. Cli P					
City Review							
Compliant Corrective Action Required							
Certificate of Compliance Expires: 1/31/2033 Corrective Action Due by:							
Date: Signature: Hellutton Name: Killie Hour							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	H" Cost / Clay
Overall Condition of Service Pipe	(2000)

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising.				
Feet	Comment			
Example: 0	Start for 4" cleanout in NE corner of Basement			
0	Misaligned joint-Infiltration 3/2" Busement bedroom S room in wall 400 PVC Cleanout			
97'	Clay to Cast Liver from Main up 3001 Main			
Notes:	JVI CUIV			