TASK 84519

Date Called in
 Date Called in
 5/6/2024

 Date Scheduled
 5/10/2024-9:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

perty Address:	1066 Loma Linda Avenue	
)•	0811723230007	

Property Address:	ss: 1066 Loma Linda Avenue		Avenue	,		144
PID:		0811723230007				
		Ovvenou I	u formation			
Name:	James	s David Nelson	nformation			
Mailing Address: (if different from Property)		5 David 11010011		, ,		
Phone:	612-59	97-1963	Email: jim.david.nelson(@gmail.con	n	
		T.,	T., C., 4! - i.			
Name:		Inspector	Information			
Company/ Organi	zation		License number:		v	2 7
Phone:			Email:			
	G. 1		ection			
System	Stand		111		Pass	Fail
Roof Drains	sewer b drains a connec	but should discharge to the gro are connected to the sanitary s ctions to the sanitary sewer using	should not be connected to the sound outside of a building. If the sewer, disconnect them, plug anying a non-shrink permanent matern outside the building.	roof open	Х	/ · · · ·
Foundation Drains	redirect the roof drains onto the ground outside the building. Foundation drains are underground pipes that collect storm water from around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.					
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.					
Sewer Service Line	Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)					
Notes:		ervice Looks		1 2	7	
Toilet Removed For Inspection:	o Yes	₹No		gs x		100 M

Inspectors Signature:	Justin	Date: < <u><</u> へんかつく
Owners Signature:		Date:

City Review				
Compliant		☐ Corrective Action Required		
Certificate of Compliance Expires: 5/6/2034		Corrective Action Due by:		
Date:	Signature:	lieloin		
5/16/2024	Name: Kellie Hoen			

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc. This report must include a digital copy of the televising. Feet Comment Example: 0 Start for 4" cleanout in NE corner of Basement 1-10 Misaligned joint –Infiltration 0 11 Mood Abs To CAST From Notes:

1.