## TASK 84884

# (LOVO)

## Date Called in 5/28/2024 Date Scheduled 5/31/2024 10:30 AM

#### City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Poi	int of Sa	ale Sanitary Sewer Serv	ice I&I Comp	liance Inspec	tion Fori	n	
Property Address:		2474 Carman Street					
PID:		2011723120027					
		2011120120021					
		Owner 1	Information				
Name: Scott		Edwards					
Mailing Address:	ling Address:						
(if different from	Booker Ellen Deheven						
Property)		Realtor Ellen Dehaven  612-817-5555  Email:   edehaven@cbrealtv.com					
Phone:	612-8	17-5555	Email: ed	ehaven@cbrea	Ity.com		
		Inspector	Information				
Name:		Sover Crawl					No. of the Section of
Company/ Organization		A. VCI CIVIC.VI	License nun	nber:			
Phone:			Email:				
				'			
		Insp	pection				
System	Stand	lard				Pass	Fail
Roof Drains		Roof drains and leaders Roof drains should not be connected to the sanitary					
		sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open					
		tions to the sanitary sewer us				X	
	redirec	t the roof drains onto the grou	and outside the bu	uilding.			
Foundation		dation drains are underground pipes that collect storm water from			n		
Drains		bund the base of a building and into a sump basket, where it is then mped outside of the building. Foundation drains should not be connected					
		anitary sewer.	muation urains sir	louid not be com	iecteu	$\wedge$	
Sump Pumps		Sump pumps are designed to capture surface or ground		round water tha	t enters		
Sump rumps	baseme	nts or crawl spaces and pump	p it away from the	e house. The bas	ic sump	V/	
		includes drain tile, a sump p				X	
Sewer Service	drain line. Sump pumps should not be connected to the sanitary sewer.  Sanitary Sewer Inflow & Infiltration (I/I) Compliance Inspection Sanitary					-	
Line		Sewer Lines. All sanitary sewer lines serving Property, from the house to the					
Line	main line, shall be in a safe and functional condition and shall be free from all						X
		ailures including but not limi rusion. The sanitary sewer lin					
		cations. (Details on back of t		City Code stand	iaius aiiu		
Notes:				alad			1
	VIUT	o reviewed by	30041 213	10 [29			
	e.	,					
Toilet Removed	○ Yes ○ No						
For Inspection:							
Inspectors Signature:			Date:				
Owners Signature: Date:							
		C:L.	Daviou		teri organici in te		
□ Com::!:-::t	10	City	Review	notivo Antinu I	Doguies 1	٢ .	
Confliant			Corrective Action Required Corrective Action Due by: 8 30 2024				
					813	114049	
Date: Signature: Signature: Name: Valla Houn							
5/30/2019 Name: Kellic Hoen							

### **Service Line Inspection Details**

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	Sch40 PVC
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.  This report must include a digital copy of the televising.						
Feet	Comment					
Example: 0 1-10	Start for 4" cleanout in NE corner of Basement Misaligned joint –Infiltration					
0						
12'	20013					
140	Main					
Notes:						