TASK 87967



Date Called in 10/7/2024 Date Scheduled 10/9/2024 10:00 AM

City Of Orono Point of Sale Sanitary Sewer Service I&I Compliance Inspection Form

Property Address:		651 Sandstone Circle					
PID:		3311823110030					
Owner Information							
Name:	Kaitlin Thompson						
Mailing Address: (if different from Property)		4		84			
Phone:	763-399-0797 Email: kt.marie704@gmail.com						
Inspector Information							
Name:			v				
Company/ Organization		,	License number:		-		
Phone:	Email:						
~ .	[a.]	The state of the s	ection		l n	177-21	
System	,	Standard Pas				Fail	
Roof Drains	Roof drains and leaders Roof drains should not be connected to the sanitary sewer but should discharge to the ground outside of a building. If the roof drains are connected to the sanitary sewer, disconnect them, plug any open connections to the sanitary sewer using a non-shrink permanent material, and redirect the roof drains onto the ground outside the building.						
Foundation			ipes that collect storm water from	n			
Drains	around the base of a building and into a sump basket, where it is then pumped outside of the building. Foundation drains should not be connected to the sanitary sewer.				·		
Sump Pumps	Sump pumps are designed to capture surface or ground water that enters basements or crawl spaces and pump it away from the house. The basic sump system includes drain tile, a sump pit, a sump pump, a float or switch, and a drain line. Sump pumps should not be connected to the sanitary sewer.						
Sewer Service Line	Sanitary Sewer Inflow, & Infiltration (I/I) Compliance Inspection Sanitary Sewer Lines. All sanitary sewer lines serving Property, from the house to the main line, shall be in a safe and functional condition and shall be free from all leaks, failures including but not limited to partially collapsed sections or tree root intrusion. The sanitary sewer lines shall meet the City Code standards and specifications. (Details on back of this sheet)						
Notes:							
Toilet Removed	o Yes	No	VIN				
For Inspection:		P					
				1 -			
Inspectors Signature: Justin Boian				Date: $[0/9/24]$			
Owners Signature: Date:						-	
City Davidous							
City Review							
Compliant Certificate of Compliance Expires: 10/9/2034 Corrective Action Due by:							
Date: Signature: Signature:							
Name: Kellic Hoen							
10/1/6007 Italio. N. IIIC TIDEN							

Service Line Inspection Details

Weather Conditions:	
Approximate Depth of Service	
Type and Size of Service	911 54 40
Overall Condition of Service Pipe	

Please note all connections, fittings, points of concern on service line including infiltration, tree root, cracks, misaligned joints, etc.						
Feet	This report must include a digital copy of the televising. Comment					
Example:	Connicit					
0	Start for 4" cleanout in NE corner of Basement					
1-10	Misaligned joint –Infiltration					
	moungiou joint minutation					
0	Clean out in basement along E wall					
*						
	90' CONTEN'T PUSK ENAKEN.					
	1 - Contain Full Kultures					
Notes:						